

Safety-Gram

Title 45, Chapter 11

March 2013

Volume 14, Number 3

AVOID JOB SITE OVERTURN

Stockpiles
and ramps
must be
bermed
correctly.

Leave a margin of error,
never push your machine
to the limit.

Slow to a safe speed prior to entering a curve.

Road surfaces
can change
dramatically
from day to
day, even hour
to hour.

Loaders should carry the
bucket low to maintain a
good center of gravity, good
visibility and to protect
from overturn.

Be Aware of the **SHAPE** you are in!