

Oklahoma Department of Mines - Revision Information

<u>REV#</u>	<u>DATESUB</u>	<u>TYPE</u>	<u>STATUS</u>	<u>APPRV/DENIED</u>	<u>PERMITTEE</u>	<u>PERMIT</u>	<u>PURPOSE OF REVISION</u>
2014F	11/13/2018	MAJ	PENDING		FCMC	12/17-4262F	POSTMINE TERRACE; ETC SEE REVISION
2013	10/25/2018	MIN	PENDING		EOQ	11/16-4272	SURFACE WATER FLOW CONTROLLED VEG
2012F	8/22/2018	MIN	WITHDRAWN	10/12/2018	BRAZIL CREEK	13/18-4254F	INCREASE COAL PAD AREA
2011	7/30/2018	MIN	APPROVED	8/8/2018	GCI	15/20-4243F	ADDITIONAL OPERATOR COAL-X/E. BALLAR
2010F	7/11/2018	MIN	APPROVED	9/19/2018	CAVANAL	13/18-4269F	ASH & RAILROAD TIE DISPOSAL
2009F	7/9/2018	MIN	APPROVED	10/1/2018	GCI	15/20-4243F	REVISE MAPS TO SHOW STRUCTURE LOCA
2008	5/10/2018	MIN	APPROVED	7/2/2018	MMHF	LE-1857	DISPOSE OF ASH PRODUCT POWER PLANT
2007	4/25/2018	MIN	APPROVED	7/16/2018	PHOENIX	17/22-4290	AS BUILT DESIGNS PONDS 105 & 107
2006	4/13/2018	MAJ	DENIED	10/23/2018	LOVE	4292	LACK OF RESPONSE
2005F	1/17/2018	MIN	APPROVED	10/31/2018	FCMC	18/23-4293F	RELOCATE EXPL STORAGE;REDES DD-5A
2004	12/28/2017	MIN	APPROVED	3/22/2018	PHOENIX	11/16-4286	-10.5 ACRES DOUBLE PERMITTED W/4290
2003	12/15/2017	MIN	APPROVED	4/10/2018	EOQ	11/16-4272	RIPRAP CHANNEL SURFACE WATER
2002	11/30/2017	MAJ	APPROVED	8/10/2018	PHOENIX	14/19-4287	AS-BUILT DESIGNS
2001	11/17/2017	MAJ	APPROVED	4/3/2018	PHOENIX	17/22-4290	MINE THROUGH SEG OF LIGHTING CREEK
2000F	11/8/2017	MAJ	APPROVED	3/23/2018	BRAZIL CREEK	13/18-4254F	INCORPORATE HIGHWAY MINING MU D
1999F	10/2/2017	MIN	APPROVED	12/29/2017	FCMC	14/19-4275F	ENHANCE WILDLIFE AREA
1998F	9/29/2017	MIN	APPROVED	7/25/2018	GCI	15/20-4243F	EXPANDS UNDERGROUND MINING
1997	6/22/2017	MIN	APPROVED	8/25/2017	PHOENIX	10/15-4283	DIVIDE PERMIT INTO 2 INCREMENTS
1996F	6/9/2017	MAJ	APPROVED	12/27/2017	FCMC	14/19-4275F	DOCUMENTS REDUCED COAL RECOVERY
1995	6/9/2017	MIN	APPROVED	11/20/2017	PHOENIX	14/19-4287	DIVIDE PERMIT INTO 4 INCREMENTS
1994	6/8/2017	MIN	APPROVED	10/26/2017	EOQ	11/16-4272	GRADED POST-MINE CONFIGURATION
1993	5/22/2017	MAJ	DENIED	10/23/2018	FCMC	12/17-4268	INCR BONDS PERMIT; LACK OF RESPONSE
1992	5/11/2017	MIN	APPROVED	7/26/2017	EOQ	11/16-4272	BOND RECALCULATION

<u>REV#</u>	<u>DATESUB</u>	<u>TYPE</u>	<u>STATUS</u>	<u>APPRV/DENIED</u>	<u>PERMITTEE</u>	<u>PERMIT</u>	<u>PURPOSE OF REVISION</u>
1991F	1/30/2017	MIN	APPROVED	3/3/2017	GCI	15/20-4243F	ADD TXOMA MINING AS OPERATOR
1990F	1/6/2017	MIN	APPROVED	8/15/2017	FCMC	14/19-4275F	LOC DD-13; +TOPSOIL PILE; DIST AREA #4