

Safety-Gram

Title 45, Chapter 11

Volume 18, Number 9

September 2017

HEAVY EQUIPMENT AROUND WATER

Section 910.7 - The supervisor or a certified person designated by him shall examine working areas and faces of walls for unsafe conditions at least at the beginning of each shift, during the shift while men are working, and after blasting. Any unsafe condition found shall be corrected before any further work is performed at the immediate area or face at which the unsafe condition exists.

Section 916.14 - Machinery and equipment shall be operated only by authorized and experienced persons.

Section 917.6 - Life jackets or belts shall be worn where there is danger of falling into deep water.

Section 919.1 - Each place of work shall be visited by a certified person at the beginning of, and at least once during, each shift and more frequently as is necessary to insure that work is being done in a safe manner.

Section 919.2 - No employee shall be assigned, allowed or required to perform work alone in any area where hazardous conditions exist that would endanger his safety unless he can communicate with others, can be heard or can be seen.

